ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
11

Ward Name
Kuvempu Nagar

Street ID
W0032, W0064, W0228, W0222, W0323, W0329, W0226, W

Street Name
NA, 10th Crs Lakshmi Sagar Lyt, Lakshmi Sagar Lyt North Side, 1st Crs

Significant Landmark
Vinayak Nagar

Segment No.
11/S-W0032/S075536

Total Length (m)
288.85

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	38.93	77.536721	13.079345	77.536560	13.079031	W0222	W0228
2	59.01	77.547008	13.081890	77.546816	13.081391	I0084	DEAD END
3	80.56	77.544697	13.082791	77.544300	13.082175	W0119	W0038
4	20.81	77.544308	13.082650	77.544477	13.082562	W0119	W0038
5	89.54	77.543483	13.083260	77.544224	13.082905	W0097	W0038

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to Road and Drains at Vinayak Nagar in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
4000000

Sanctioned Year
2016

Year
2016 - 2017

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Improvements to Road and Drains at Vinayak Nagar in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone

Job No. / Work Code
011-16-000002

Work Order No.
BBMP/EE/BTP/WO/103/2016-17

Work Order Date
09/08/2016

Period of Extention
60 DAYS

Defect Liability Period From
09/08/2016

Defect Liability Period To
08/08/2017

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)

B B UMESHA	0.00

Phone No. **E-Mail ID**

9886213563

Field Inspection Details

Number of Trees	Any Other Information	Name
0		SURESH
Date of Inspection	**Remarks**	
14/09/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0032, W0064, W0228, W0222,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	14/09/2016	14/10/2016	COMPLETED
SE	VASU K M	14/09/2016	14/10/2016	COMPLETED
EE	YARAPPA REDDY	14/09/2016	14/10/2016	COMPLETED
AEE	SHIVAKUMAR	14/09/2016	14/10/2016	COMPLETED
AE	SURESH	14/09/2016	14/10/2016	COMPLETED
AE	SURESH	14/09/2016	14/10/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0032, W0064, W0228, W0222,